

#### **UNITED STATES ENVIRONMENTAL PROTECTION AGENCY**

## REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

HRE-8J

November 24, 1992

Mr. Mark Fehlmann Environmental Manager American Tape Company 317 Kendall Avenue Marysville, MI 48040

Re:

Visual Site Inspection American Tape Company Marysville, Michigan MID 061 862 926

Dear Mr. Fehlmann:

As indicated in the letter of introduction sent to you on March 11, 1992, the U.S. Environmental Protection Agency is enclosing a copy of the final Preliminary Assessment/Visual Site Inspection (PA/VSI) report for the referenced facility. The executive summary and conclusions and recommendations sections have been withheld as Enforcement Confidential.

If you have any questions, please call Francene Harris at (312) 886-2884.

Sincerely yours,

Kevin M. Pierard, Chief

Minnesota/Ohio Technical Enforcement Section

RCRA Enforcement Branch

PRC Environmental Management, Inc. 233 North Michigan Avenue Suite 1621 Chicago, IL 60601 312-856-8700 Fax 312-938-0118



#### PRELIMINARY ASSESSMENT/ VISUAL SITE INSPECTION

AMERICAN TAPE COMPANY MARYSVILLE, MICHIGAN MID 061 862 926

FINAL REPORT

#### Prepared for

## U.S. ENVIRONMENTAL PROTECTION AGENCY Office of Waste Programs Enforcement Washington, DC 20460

Work Assignment No.

R05032

EPA Region

5

Site No.

Date Prepared

MID 061 862 926 November 11, 1992

Contract No.

68-W9-0006

PRC No.
Prepared by

309-R05032MI22 PRC Environmental Management, Inc.

Contractor Project Manager

(Jeff Swano) Shin Ahn

Contractor Project Manager Telephone No.

(312) 856-8700

EPA Work Assignment Manager

Kevin Pierard

Telephone No.

(312) 886-4448

## TABLE OF CONTENTS

Section	<u>1</u>															<u>Pa</u>	<u>ige</u>
EXEC	UTIVE	SUMM	ARY							• • •		 . ,	 			ES	-1
1.0	INTRO	DUCT	ION									 	 		. <b>.</b> .		1
2.0	FACIL	ITY DI	ESCRIPTION									 	 				3
	2.1 2.2 2.3 2.4 2.5 2.6	FACIL WASTI HISTO REGU	ITY LOCATI ITY OPERATE E GENERATE RY OF DOCU LATORY HIS RONMENTAL	TIONS ION AN JMENT STORY	D MA	 NAG ELEA	EMI SES	ENT	• • •			 	   	  			
		2.6.1 2.6.2 2.6.3 2.6.4	Climate Flood Plain a Geology and Ground Wate	nd Surfa Soils .	ace Wa	iter .			 		<i>.</i>	 	  				16 17 17 17
	2.7	RECE	PTORS									 	 				18
3.0	SOLID	WAST	E MANAGEM	1ENT U	NITS			:				 	 	<b></b> .			20
4.0	AREA	S OF C	ONCERN									 	 	• • •			28
5.0	CONCLUSIONS AND RECOMMENDATIONS							29									
REFE	RENCE	s	• • • • • • • • • •		<i></i>							 	 	<b>.</b>			35
Attach	ment																
A	VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS																
В	VISUAL SITE INSPECTION FIELD NOTES																

# LIST OF TABLES

<u>Table</u>	Page	
1	SOLID WASTE MANAGEMENT UNITS 6	
2	SOLID WASTES 8	
3	SWMU AND AOC SUMMARY 33	
•		
	LIST OF FIGURES	
	LIST OF FIGURES	
<u>Figure</u>	rage	
1	FACILITY LOCATION 4	
2	FACILITY LAYOUT	

# ENFORCEMENT CONFIDENTIAL

#### **EXECUTIVE SUMMARY**

PRC Environmental Management, Inc. (PRC), performed a preliminary assessment and visual site inspection (PA/VSI) to identify and assess the existence and likelihood of releases from solid waste management units (SWMU) and other areas of concern (AOC) at the American Tape Company (ATC) facility in Marysville, St. Clair County, Michigan. This summary highlights the results of the PA/VSI and the potential for releases of hazardous wastes or hazardous constituents from SWMUs and AOCs identified.

The ATC facility manufactures pressure-sensitive, solvent-based adhesive tapes. The facility generates and manages the following waste streams: solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), silicone, cleaning rags and filter socks (D001 and F005), resin oven drippings, waste water-soluble oil, waste oil, contaminated and off-specification solvents (D001), oven dust, and spent activated carbon. ATC has operated at its current location since 1983. The facility occupies about 11.2 acres in an industrial park and employs about 340 people. The facility is currently regulated as a treatment, storage or disposal facility pending closure of the Former Hazardous Waste Storage Area (SWMU 8).

The Dow Magnesium Corporation built the ATC facility during World War II and operated it as a munitions plant. After the war, the property was sold off in separate parcels to numerous parties as part of the Surplus Land Act of 1946. In 1962, American Pres-Stik Tape Company (APT) and K&K Investments (K&K) purchased the bulk of the facility and began tape manufacturing operations. In 1965, APT and K&K sold their operations to Armour Company (Armour) who continued to manufacture tape. In 1966, Armour purchased the warehouse parcel and expanded the facility. In January 1971, Armour sold the facility to the Armak Company who, in 1983, sold it to ATC. In July of 1990, ATC's stock was sold to the Seoul Trading Company of North America (STCNA), a Korean-based concern. Currently, STCNA owns the property and ATC operates the facility.

The facility filed a Part A permit application on April 29, 1983 for its Former Hazardous Waste Storage Area (SWMU 8). This unit is currently undergoing RCRA closure.

The PA/VSI identified the following nine SWMUs and two AOCs at the facility:


RELEASED ( )

## Solid Waste Management Units

- 1. Hazardous Waste Storage Area
- 2. Solvents Satellite Accumulation Area
- 3. Gaylord Boxes
- 4. Nonhazardous Liquid Wastes Storage Areas
- 5. Oil/Water Satellite Accumulation Area
- 6. Waste Adhesive Satellite Accumulation Area
- 7. Paint Waste Satellite Accumulation Areas
- 8. Former Hazardous Waste Storage Area
- 9. Isopropanol Satellite Accumulation Area

#### Areas of Concern

- 1. USTs No. 202 and 203
- 2. USTs No. 1 through 3



The facility is located in an area of highly impermeable clay deposits that are about 140 feet thick. This clay unit does not have enough water-bearing capacity to characterize it as an aquifer. Ground water is obtained from the shale bedrock aquifer underlying the clay deposits, and is used as a drinking water source west and upgradient of the facility. Drinking water in the area of the site is primarily obtained from the St. Clair River located 1,400 feet east of the facility. The nearest surface water intakes are located about 1.75 miles north and upstream of the facility.

The potential for release to ground water, surface water, air, and on-site soils from most of the SWMUs is low because the units are maintained indoors and on concrete floors that are in good condition. However, the potential for a release to air from the Hazardous Waste Storage Area (SWMU 1) is moderate because the unit has no walls and is used to store highly volatile solvents; any accidental spill at the unit would result in a release to the air. In addition, the potential of a release to air from USTs No. 202 and 203 (AOC 1) was moderate because, at the time of the inspection, the concrete over the tanks was removed and solvent-contaminated soils were exposed and likely to volatilize. Releases to surface water have occurred in the past due to raw material solvent spills reaching facility storm water sewers; these sewers empty into an unnamed ditch, which flows into the St. Clair River. Subsurface soil and ground water contamination caused by leakage from underground storage tanks (UST) (AOCs 1 and 2) has been documented at the facility. At the time of the inspection, ATC was working on getting state approval for its remediation plans. ATC intends to replace the leaking USTs and remediate contamination at the facility.

PRC recommends closure activities for the Former Hazardous Waste Storage Area (SWMU 8) continue as scheduled. In addition, remedial activities planned for the leaking USTs (AOCs 1 and 2) should proceed as planned once those plans are approved by the state.

#### 1.0 INTRODUCTION

PRC Environmental Management, Inc. (PRC), received Work Assignment No. R05032 from the U.S. Environmental Protection Agency (EPA) under Contract No. 68-W9-0006 (TES 9) to conduct preliminary assessments (PA) and visual site inspections (VSI) of hazardous waste treatment and storage facilities in Region 5.

As part of the EPA Region 5 Environmental Priorities Initiative, the RCRA and CERCLA programs are working together to identify and address RCRA facilities that have a high priority for corrective action using applicable RCRA and CERCLA authorities. The PA/VSI is the first step in the process of prioritizing facilities for corrective action. Through the PA/VSI process, enough information is obtained to characterize a facility's actual or potential releases to the environment from solid waste management units (SWMU) and areas of concern (AOC).

A SWMU is defined as any discernible unit at a RCRA facility in which solid wastes have been placed and from which hazardous constituents might migrate, regardless of whether the unit was intended to manage solid or hazardous waste.

The SWMU definition includes the following:

- RCRA-regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that EPA has
  usually exempted from standards applicable to hazardous waste
  management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents. Such areas might include a wood preservative drippage area, a loading or unloading area, or an area where solvent used to wash large parts has continually dripped onto soils.

An AOC is defined as any area where a release to the environment of hazardous waste or constituents has occurred or is suspected to have occurred on a nonroutine and nonsystematic basis. This includes any area where a strong possibility exists that such a release might occur in the future.

The purpose of the PA is as follows:

- Identify SWMUs and AOCs at the facility
- Obtain information on the operational history of the facility
- Obtain information on releases from any units at the facility
- Identify data gaps and other informational needs to be filled during the VSI

The PA generally includes review of all relevant documents and files located at state offices and at the EPA Region 5 office in Chicago.

The purpose of the VSI is as follows:

- Identify SWMUs and AOCs not discovered during the PA
- Identify releases not discovered during the PA
- Provide a specific description of the environmental setting
- Provide information on release pathways and the potential for releases to each medium
- Confirm information obtained during the PA regarding operations,
   SWMUs, AOCs, and releases

The VSI includes interviewing appropriate facility staff; inspecting the entire facility to identify all SWMUs and AOCs; photographing all visible SWMUs; identifying evidence of releases; making a preliminary selection of potential sampling parameters and locations, if needed; and obtaining additional information necessary to complete the PA/VSI report.

This report documents the results of a PA/VSI of the American Tape Company (ATC) facility (EPA Identification No. MID 061 862 926) in Marysville, St. Clair County, Michigan. The PA was completed on March 5, 1992. PRC gathered and reviewed information from the Michigan Department of Natural Resources (MDNR) and from EPA Region 5 RCRA files. The VSI was conducted on March 25, 1992. It included interviews with a facility representative and a walk-through inspection of the facility. PRC identified nine SWMUs and two AOCs at the facility.

The VSI is summarized and nine inspection photographs are included in Attachment A. Field notes from the VSI are included in Attachment B.

#### 2.0 FACILITY DESCRIPTION

This section describes the facility's location; past and present operations; waste generating processes and waste management practices; a history of documented releases; regulatory history; environmental setting; and receptors.

#### 2.1 FACILITY LOCATION


The ATC facility is located at 317 Kendall Avenue in Marysville, St. Clair County, Michigan. Figure 1 shows the location of the facility in relation to the surrounding topographic features (latitude 82° 28' 057" N and longitude 42° 53' 041" W). The facility occupies about 11.2 acres in the South Marysville Industrial Area industrial park.

The facility is bordered on the north by Kendall Avenue, a manufacturing facility, and a parking lot; on the west by Wills Street and an open lot; on the south by an open lot and an abandoned building; and on the east by Vicksburgh Street and an open lot. Mills Street bisects the facility.

## 2.2 FACILITY OPERATIONS

The Dow Magnesium Corporation built the ATC facility during World War II and operated it as a munitions plant. After the war, the property was sold off in separate parcels to numerous parties as part of the Surplus Land Act of 1946. In 1962, American Pres-Stik Tape Company (APT) and K&K Investments (K&K) purchased the bulk of the facility and begin tape manufacturing operations. In 1965, APT and K&K sold their operations to Armour Company (Armour) who continued to manufacture tape. In 1966, Armour purchased the warehouse parcel and expanded the facility. In January 1971, Armour sold the facility to the Armak Company who, in 1983, sold it to ATC. In July of 1990, ATC's stock was sold to the Seoul Trading Company of North America (STCNA), a Korean-based concern. Currently, STCNA owns the property and ATC operates the facility.

ATC manufactures pressure-sensitive, solvent-based adhesive tapes. The raw materials used during manufacturing and stored in warehouses include natural rubber, isopropanol, and rolls of tape. Solvents are used extensively and stored in underground storage tanks (UST).



The manufacturing process consists of three stages: adhesive mixing, coating, and slitting. Natural rubber is the primary raw material for the adhesive mixing process. Zinc oxide and clay, which are purchased in bags, are added to the rubber and mixed. This mixture is pumped to a churn for more mixing and then stored in a warehouse in tote containers.

The coating process applies the adhesive to rolls of tape purchased off site, which are made of paper, film, or fiberglass. ATC operates three separate coating lines, depending on the type of tape being coated at the time, and nine drying ovens. As the rolls of tape are unwound, they receive a release coating on the back side, necessary in order to remove tape from a roll, and the adhesive coating on the front side. There are several different types of release coatings used at the ATC facility. Resins and solvents (xylene and toluene) are mixed to produce the release coating for most tapes. The release coating for reinforced tapes contains isopropanol. The release coating for some masking tapes is a water-based silicone. The coatings are dried in ovens and then the tape is wound up and stored. Solvent-laden air passes through a solvent recovery system at the coating lines. The solvent is recycled and used in making adhesives.

The rolls of coated tape become final product during the slitting process. The rolls are unwound and cut into finished sizes and rewound on individual cardboard cores. The rolls are dusted with plastic pellets to keep them from sticking together and are then wrapped in plastic. The wrapped bundles are packed into cartons and stored in a warehouse or shipped directly to the customer.

Solid wastes generated from ATC facility operations and the SWMUs where they are managed are discussed in detail in Section 2.3.

The ATC facility is comprised of four buildings: Building No. 7 used for maintenance and storage, Building No. 48 comprised of storage and a boiler plant, and the solvent recovery building are on the west side of Mills Street; and the manufacturing facility building is on the east side of Mills Street. This occupies approximately 650,000 square feet. The facility operates 3 shifts per day, 7 days per week, and employs about 340 people.

## 2.3 WASTE GENERATION AND MANAGEMENT


Wastes are generated and managed at various locations at the facility. SWMUs and their current status are identified in Table 1. The locations of SWMUs and AOCs in relation to the facility layout are shown in Figure 2. Wastes generated at the facility are summarized in Table 2. Facility generation and management of both hazardous and nonhazardous wastes are discussed below.

TABLE 1
SOLID WASTE MANAGEMENT UNITS

Active, storage of hazardous wastes for less than 90 days
Active
Active
Active, storage of nonhazardous liquid wastes
Active, storage of oil and water mixture to separate oil and water
Active
Active
Inactive as of 1990; undergoing RCRA closure
Active

Note:

A RCRA hazardous waste management unit is one that currently requires or formerly required submittal of a RCRA Part A or Part B permit application.



## TABLE 2 SOLID WASTES

Waste/EPA Waste Code <sup>a</sup>	Source	Solid Waste <u>Management Unit<sup>b</sup>,</u>			
Solvent-contaminated waste oil/D001	Adhesive mixing process	1, 5, and 8			
Waste Adhesive/D001	Adhesive mixing process	1, 6, and 8			
Paint Waste/D001	Coating process	1, 7, and 8			
Waste Isopropanol/D001	Coating process	1, 8 and 9			
Silicone/NA	Coating process	4			
Cleaning Rags and Filter Socks/D001 and F005	Adhesive mixing process, coating process	3			
Resin Oven Drippings/NA	Coating process	4			
Waste Water-Soluble Oil/NA	Slitting process	4			
Waste Oil/NA	Vehicles and Machinery	4			
Contaminated and Off-Specification Solvents/D001	Adhesive mixing process	1, 2, and 8			
Oven Dust/NA	Slitting process	1			
Spent Activated Carbon/NA	Solvent recovery	None			

# Notes:

Not applicable (NA) designates nonhazardous waste.

b "None" indicates that the waste stream is not managed on site.

Primary waste streams routinely generated at the facility include solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), nonhazardous silicone, solvent-contaminated cleaning rags and filter socks (D001 and F005), nonhazardous resin oven drippings, nonhazardous waste water-soluble oil, and nonhazardous waste oil. Wastes generated on a nonroutine basis include contaminated and off-specification solvents (D001), nonhazardous oven dust, and nonhazardous spent activated carbon. All wastes are generated directly from the manufacturing process except for waste oils, which are generated indirectly from manufacturing machinery, and spent activated carbon which is generated from solvent recovery operations.

Prior to June 1990, solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), and contaminated or off-specification solvents (D001) were stored at the Former Hazardous Waste Storage Area (SWMU 8).

Oil drips from the moving parts of the adhesive mixing machinery into catch basins around the machinery. Condensate also drips from the machinery and mixes with the oil. Solvents splash into the catch basins during mixing and contaminates the water. This oil/water mixture is collected in 5-gallon buckets and placed in the Oil/Water Satellite Accumulation Area (SWMU 5). This unit consists of a 55-gallon drum and is used to separate the oil/water mixture. When the drum is full, the oil is drained from the bottom of the drum, placed into 5-gallon buckets and reworked into the machinery. The water is then drained from the unit into 5-gallon buckets, and transferred to 55-gallon drums at the Hazardous Waste Storage Area (SWMU 1) for less than 90-day storage. The water is transported off site as solvent-contaminated waste oil (D001) by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton, Ohio to be incinerated.

Waste adhesive (D001) is generated when an adhesive batch can no longer be used as a coating. In addition, piping carrying adhesives is occasionally cleaned, also producing waste adhesive. These wastes are accumulated in a plastic-lined 55-gallon drum at the Waste Adhesive Satellite Accumulation Area (SWMU 6) and then stored for less than 90 days at the Hazardous Waste Storage Area (SWMU 1). The drums are transported off site by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton.

Resins, which are purchased in bags, and solvents (xylene, toluene) are mixed to produce a release coating applied to the back of the tape. Residue at the bottom of 55-gallon drums used for mixing the release coating is disposed of as paint waste (D001). While these wastes are not paint, the facility refers to them as paint wastes because of their resin and solvent constituents. These wastes are consolidated in a Paint Waste Satellite Accumulation Area (SWMU 7) located in

the adhesive mixing room. Paint waste is also generated at the coating lines and stored in a second Paint Waste Satellite Accumulation Area (SWMU 7). All drums of paint waste are then stored for less than 90 days in the Hazardous Waste Storage Area (SWMU 1). About 18,550 gallons were generated in 1991. The drums are transported off site by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton.

Isopropanol is used as a release coating for reinforced tape. Waste isopropanol (D001) is generated at various points along the coating lines and stored in 55-gallon drums at the Isopropanol Satellite Accumulation Area (SWMU 9). When a drum is full, it is covered and transferred to the Hazardous Waste Storage Area (SWMU 1). About 292 gallons were generated in 1991. Laidlaw Environmental Services of Corunna, Ontario, Canada transports the wastes to their liquid injection incinerator in Corunna.

A water-based silicone release coating is applied to paper masking tape lines. Nonhazardous waste silicone is generated from residuals and drippings at the coating lines. The wastes are accumulated in 55-gallon drums and stored in 275-gallon plastic tanks enclosed in 4-foot by 4-foot cardboard boxes at the Nonhazardous Liquid Wastes Storage Area (SWMU 4) in Building No. 48. Laidlaw Environmental Services of Corunna, Ontario, Canada empties the containers and transports the wastes to their liquid injection incinerator in Corunna.

Solvent-saturated cleaning rags (D001 and F005) are generated throughout the facility during daily cleanup operations around all machinery. These wastes are disposed of in Gaylord Boxes (SWMU 3) which are 4-foot by 4-foot by 4-foot high plastic-lined boxes situated in two areas of the facility. Gaylord Boxes (SWMU 3) are also used for the disposal of filter socks (D001 and F005). Filter socks are generated at several filtering stations used to screen particulates from the adhesive. The rags, filter socks, and empty resin bags are all disposed of in Gaylord Boxes (SWMU 3). The boxes are transported off site and manifested as contaminated debris by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton, Ohio.

Nonhazardous resin oven drippings are generated at the coating lines from the ovens' extreme heat, which liberates oils and resins. The drippings are collected in 55-gallon drums and stored at the Nonhazardous Liquid Wastes Storage Area (SWMU 4) in Building No. 7. The drums are emptied and the wastes are transported off site in tanker trucks by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton.

A nonhazardous waste water-soluble oil is a lubricating solution generated from the cutting knives of the slitter machinery. These wastes are accumulated in 55-gallon drums and

then stored at the Nonhazardous Liquid Wastes Storage Area (SWMU 4) in Building No. 48. Laidlaw Environmental Services of Corunna, Ontario, Canada empties the containers and transports the wastes to their liquid injection incinerator in Corunna.

Nonhazardous waste oil is generated from maintenance on facility vehicles and machinery. This waste is stored in 55-gallon drums in the Nonhazardous Liquid Wastes Storage Area (SWMU 4) in Building No. 7. Safety-Kleen of Pontiac, Michigan collects the waste oil, manifests it as nonhazardous liquid waste, and transports it to their bulking facility in Pontiac, Michigan. The oil is then transported by railroad car to Safety-Kleen fuel blending facility in East Chicago, Indiana.

Occasionally, contaminated and off-specification solvents (D001) are generated. Waste solvents generated during adhesive production are accumulated at the Solvents Satellite Accumulation Area (SWMU 2) and stored at the Hazardous Waste Storage Area (SWMU 1). Solvents are also generated at the solvent recovery building. When the solvents become too dirty to reuse, they are immediately placed in 55-gallon drums and stored at the Hazardous Waste Storage Area (SWMU 1). When the facility receives a batch of off-specification solvents, they are immediately stored in the 55-gallon containers in which they came, as is the case with xylene, or they are transferred into 55-gallon drums from storage tanks and stored at the Hazardous Waste Storage Area (SWMU 1). Laidlaw Environmental Services of Corunna, Ontario, Canada, transports the wastes to their liquid injection incinerator.

Nonhazardous oven dust is generated during oven cleaning at a coating line. Deposits build up in the drying ovens from burning solvent-laden air. This dust contains zinc, but is not a hazardous waste. The oven dust is collected once a year during facility shutdown in 55-gallon drums and stored at the Hazardous Waste Storage Area (SWMU 1). The drums are transported off site by Ross Transportation of Grafton, Ohio to the Ross Incineration Services incinerator in Grafton.

The solvent recovery system uses four fixed-bed carbon absorption units, which were installed in 1982. In 1988, all carbon was removed from two of the units and regenerated by Envirotrol, Inc. of Sewickley, Pennsylvania. In 1989, all carbon was removed from the other two units and replaced with virgin material by Envirotrol, Inc.

## 2.4 HISTORY OF DOCUMENTED RELEASES

This section discusses the history of documented releases to ground water, surface water, air, and on-site soils at the facility.

On June 30, 1983, a 25-gallon solvent spill occurred due to overfilling of an UST in the area of UST No. 1 through 3 (AOC 2). The spill entered facility storm sewers which empty into an unnamed ditch located off site about 660 feet east of the facility. This ditch flowed into the St. Clair River until 1991 when it was replaced by a storm water sewer line that flows into the St. Clair River. The spill was contained using a floating boom and cleaned up from the ditch. The facility contacted MDNR and the Marysville Fire Department. No information is available on whether any regulatory action occurred (ATC, 1983c).

On November 16, 1983 about 100 gallons of toluene were spilled at USTs No. 1 through 3 (AOC 2). The spill occurred when a loading hose came off the tanker truck delivering the solvent. The facility covered storm drains with plastic and sand, but toluene had already entered the sewer system. Weirs were placed into the off site unnamed ditch to contain the spill, which was cleaned up within 2.5 hours. The facility contacted the Marysville Fire Department and MDNR. The facility took several actions recommended by MDNR to prevent this type of spill from occurring in the future (ATC, 1983d; MDNR 1983).

On April 3, 1986, a 100-gallon volatile chemicals mixture spill occurred indoors due to a hose uncoupling from a diaphragm pump. About 20 gallons entered facility storm sewers through cracks around a floor-drain standpipe. The facility flushed the drain with water and sampled the off site unnamed ditch. The spill reached the ditch, but no action was taken to clean up the spill. No documentation exists whether the spill reached the St. Clair River. The facility contacted the U.S Coast Guard (USCG) and MDNR (ATC, 1986).

On April 20, 1988, a 600-gallon toluene spill occurred due to human error during solvent delivery at UST No. 2 (AOC 2). The facility estimated that about 300 gallons entered facility storm drains, the off site unnamed ditch, and the St. Clair River. The facility placed weirs at the sewer discharge area in the ditch to contain the spill. Marine Pollution Control cleaned up the spill using absorbent sweeps, pumps, and weirs. The facility notified USCG, MDNR, and the Marysville Fire Department. MDNR personnel approved the cleanup and directed the facility to dispose of on-site soil affected by the spill (ATC, 1988; MDNR, 1988b). USCG fined the facility \$600.00 for violating the Federal Water Pollution Control Act (USCG, 1989). The facility contracted Great Lakes Environmental (GLE) to excavate the contaminated soil. GLE tested the soil and did not detect solvents. The soil was drummed and disposed of off site by Wayne Disposal, Inc. of Dearborn Michigan at a Class II landfill in Wayne County, Michigan (ATC, 1989b).

On September 27, 1988, a 150-gallon toluene spill occurred in the area of USTs No. 1 through 3 (AOC 2) due to the rupture of a coupling hose. The spill entered facility storm sewers and the off site unnamed ditch. The spill was contained in the ditch using absorbent pads and weirs (MDNR, 1988c). No information is available on whether any enforcement action occurred.

On April 18, 1989, a 348-gallon liquid silicone spill occurred due to the failure of an overflow alarm during tank filling. The spill entered facility storm sewers, the off site unnamed ditch, and the St. Clair River. The facility flushed the storm sewer to dilute the liquid and replaced the alarm (MDNR, 1989b). No information is available on whether any enforcement action occurred.

In 1990, the city of Marysville replaced the off site unnamed ditch with an underground storm water sewer. The new sewer is connected to facility storm water sewers and leads directly to the St. Clair River. The new sewer was constructed to have a high-retention time in case of future spills at the facility. The unnamed ditch no longer exists (PRC, 1992).

On April 26, 1991, a 10-gallon nonhazardous, diluted, polyvinyl acetate emulsions material spill occurred due to human error. The spill entered facility storm sewers. The storm drain was flushed with water. The facility contacted USCG, MDNR, EPA, Michigan Department of Public Health, the St. Clair County Emergency Preparedness Officer, and the Marysville Fire Department (ATC, 1991). No information is available on whether any enforcement action occurred.

Directly beneath the Former Hazardous Waste Storage Area (SWMU 8) are USTs No. 1 through 3 (AOC 2), once used for storing product toluene and rubber solvent. These 12,000-gallon steel tanks were installed in the late 1960s and have apparently contributed to the ground water and soil contamination in the area. In July 1991, all the tanks were closed in place. Closure consisted of emptying the tanks, cleaning them, and filling them with cement; no pressure-testing occurred (PRC, 1992).

ATC contracted with Techna Corporation (Techna) of Plymouth, Michigan, to perform UST closure activities at the facility. Sampling of subsurface soils beneath the Former Hazardous Waste Storage Area (SWMU 8) in July 1990, identified elevated levels of benzene, toluene, ethyl benzene, and xylene (Techna, 1991). The Former Hazardous Waste Storage Area (SWMU 8) was used to store solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), and contaminated and off-specification solvents (D001). Numerous spills of raw material toluene and rubber solvents have occurred at USTs No. 1 through 3 (AOC 2) located directly beneath the Former Hazardous Waste Storage Area (SWMU 8). Therefore, the

contamination identified was associated with the USTs rather than the storage area. As a consequence, Techna submitted an amended closure plan to the state to address the contamination in conjunction with the RCRA closure of the Former Hazardous Waste Storage Area (SWMU 8), which is located above the USTs. Currently, the facility plans to delineate the extent of contamination, pump and treat the ground water, and perform in situ remediation of the soil pending state approval of the amended closure plan.

USTs No. 4 through 9 are raw material tanks located directly west of USTs No. 1 through 3 (AOC 2) and under a facility building. Two 12,000-gallon steel tanks stored blended solvent, one 12,000-gallon steel tank stored process oil, one 10,000-gallon steel tank stored isopropanol, and one 2,000-gallon steel tank and one 8,000-gallon tank were empty. All of these tanks were installed in the late 1960s and closed in place in July 1990. Closure consisted of emptying the tanks, cleaning them, and filling them with cement; no pressure-testing occurred (PRC, 1992).

In July 1990, Techna also discovered VOC ground water and soil contamination at USTs No. 202 and 203 (AOC 1) once used for storing virgin and recovered solvents. The discovery was made when the facility removed the concrete slab over the tanks to install new fill ports (PRC, 1992). Apparently the tanks leaked recovered and virgin solvents. The facility notified MDNR and the Marysville Fire Department (PRC, 1992). These 20,000-gallon steel tanks were installed in 1982. The tanks were removed in June 1992 along with UST No. 201. New underground storage tanks have been installed at the location of UST No. 201. The new tanks are double-walled, with interstitial monitoring, constructed of a fiberglass composite outer wall, and lined with an epoxy coating. The facility plans to remediate the soil via in situ air stripping pending state approval (PRC, 1992).

Directly east of USTs No. 202 and 203 (AOC 1) was UST No. 201. This tank was a 30,000-gallon steel tank used to store No. 2 fuel oil. This tank was installed in 1982, filled once, and never used. This tank was not leak-tested, and it was excavated in June 1992 along with USTs No. 202 and 203 (AOC 1). The new USTs have been installed in the area of this tank (PRC, 1992).

#### 2.5 REGULATORY HISTORY

The Armak Company submitted a Notification of Hazardous Waste Activity form to EPA on August 18, 1980 (Armak, 1980). ATC submitted a RCRA Part A permit application on April 29, 1983, listing container storage (S01) of an unspecified capacity for D001 waste (ATC, 1983a). EPA notified the facility of its design capacity omission (EPA, 1983). The facility

responded with a revised Part A indicating the design capacity of the container storage area to be 12,000 gallons (ATC, 1983b).

MDNR conducted RCRA facility inspections at the ATC facility on October 22, 1985; February 25, 1988; March 8, 1989; March 29, 1990; and March 19, 1991 (MDNR, 1985; MDNR, 1988a; MDNR, 1989a; MDNR 1990a; and MDNR 1991a). All but the first inspection resulted in a notice of violations from the State of Michigan. Most violations involved improper labeling of waste containers and paperwork deficiencies. The March 19, 1991 inspection cited the company for excessive amounts of waste at a satellite accumulation area (probably SWMU 6) (MDNR, 1991a). MDNR also showed concern over inadequate secondary containment structure and poor housekeeping efforts around the storage area. The facility addressed all violations in a timely manner and MDNR determined that the violations had been properly corrected (MDNR, 1991b).

On June 21, 1988, the facility submitted a TSD operating license application for the Former Hazardous Waste Storage Area (SWMU 8). By March 23, 1989, the facility requested to withdraw its operating license application and instead develop a Part A Closure Plan for the storage area (ATC, 1989a).

The ATC facility submitted its closure plan for the Former Hazardous Waste Storage Area (SWMU 8) on June 29, 1989. The facility submitted a revised closure plan on April 19, 1990, which was approved by MDNR on June 15, 1990 (MDNR, 1990b). In June 1990 the ATC facility opened the Hazardous Waste Storage Area (SWMU 1) for less than 90-day storage of hazardous waste only.

The facility contracted with Techna to implement the approved closure plan. Sampling of subsurface soils beneath the Former Hazardous Waste Storage Area (SWMU 8) in July 1990, identified elevated levels of benzene, toluene, ethyl benzene, and xylene (Techna, 1991). The Former Hazardous Waste Storage Area (SWMU 8) was used to store solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), and contaminated and off-specification solvents (D001). Numerous spills of raw material toluene and rubber solvents have occurred at USTs No. 1 through 3 (AOC 2) located directly beneath the Former Hazardous Waste Storage Area (SWMU 8). Therefore, the contamination identified was associated with the USTs rather than the storage area. On April 29, 1991, Techna submitted an amendment to the closure plan to pump and treat contaminated ground water and in situ remediation of contaminated soils (Techna, 1991). At the time of the VSI, the Former Hazardous Waste Storage Area (SWMU 8) had not been closed.

The facility currently operates as a Large Quantity Generator due to the large amounts of paint waste (D001) and waste adhesive (D001) generated. These wastes are stored for less than 90 days at the Hazardous Waste Storage Area (SWMU 1). The facility is currently regulated as a TSD facility pending closure of the Former Hazardous Waste Storage Area (SWMU 8).

The facility currently has five operating air permits regulating: Coating Line No. 4; coating and drying ovens for Lines No. 1, 3 and a pilot line; a boiler; the Solvent Recovery Unit; and a spray booth. The facility has not violated its air permits. The facility has no history of odor complaints from workers or area residents.

The facility currently has one National Pollutant Discharge Elimination System (NPDES) permit, No. MI 0039021, for Outfall No. 001 to the St. Clair River, located about 1,400 feet east of the facility. ATC discharges about 1,000 gallons of water per day from cooling tower bleed-off and boiler condensate. All water discharged from the outfall is non-contact water. Since late 1990, facility floor drains and storm sewers empty into a storm water sewer line which flows into the St. Clair River. Prior to late 1990, storm water sewers and floor drains emptied into an unnamed ditch located 660 feet east of the facility. While there have been releases to the former unnamed ditch (see Section 2.4), the facility has not violated its NPDES permit requirements.

## 2.6 ENVIRONMENTAL SETTING

This section describes the climate; flood plain and surface water; geology and soils; and ground water in the vicinity of the facility.

### 2.6.1 Climate

The climate in the St. Clair County area is temperate and influenced by the location with respect to major storm tracks and the Great Lakes. The average daily temperature is 48.5 degrees Fahrenheit (°F). The lowest average daily temperature is 22°F in January. The highest average daily temperature is 72°F in July [U.S. Department of Commerce (USDC), 1989].

The total annual precipitation for the area is 32 inches (USDC, 1989). The mean lake evaporation for the area is about 30 inches. The 1-year, 24-hour maximum rainfall is about 2 inches (USDC, 1968).

The prevailing wind is from the southwest. Average wind speed is highest in November at 8.9 miles per hour (USDC, 1989).

## 2.6.2 Flood Plain and Surface Water

The ATC facility is not in a flood-prone area. The facility lies outside of the flood plain of the St. Clair River, located 1,400 feet east of the facility (Techna, 1988). This surface water body is used for municipal water supply, industrial, irrigation, and recreational purposes. The St. Clair River flows south to Lake St. Clair which ultimately flows into Lake Erie.

The ATC facility is mostly flat and paved. Storm water runoff drainage is directed towards storm sewers throughout the facility. The storm sewers formerly led to an off site unnamed drainage ditch which flowed into the St. Clair River. In late 1990, the city of Marysville replaced the ditch with a storm sewer line directly from the facility to the St. Clair River. Facility sanitary sewers are connected to the city of Marysville sanitary sewers, which flow to the Marysville water treatment plant located 1.5 miles north of the facility.

### 2.6.3 Geology and Soils

On-site soils have been characterized by Warzyn during borehole development for a Phase II environmental assessment of the ATC facility. Fill material overlies the natural soils of the area. The fill material consists of sand with varying amounts of silt and gravel, and ranges from 2 to 13 feet in thickness. Underlying the fill is a 140-foot thick layer of silty clay. This Pleistocene age material consists of lacustrine clays deposited in a post-glacial lake (Warzyn, 1990).

Mississippian age shale bedrock underlies the Pleistocene glacial deposits. This shale bedrock is of the Bedford and Antrim formations (Warzyn, 1990).

#### 2.6.4 Ground Water

Ground water encountered at the ATC facility is primarily perched in the sandy fill material. The sandy fill is located in pockets across the facility which do not appear to be hydraulically connected, nor do they contain amounts of water significant enough to justify defining them as aquifers (Warzyn, 1990). The clay underlying the fill material does not produce significant amounts of water. Therefore, the bedrock shale is the only aquifer in the area of the site. As discussed in Section 2.4, contamination of perched ground water in the fill has been documented at the site. However, none has been documented in the clay (Warzyn, 1990). Currently the facility plans to pump and treat contaminated ground water pending state approval of remediation plans.

Regional ground water flow direction is east toward the St. Clair River (Warzyn, 1990). The St. Clair River is about 25 feet deep in the vicinity of the facility (USGS, 1991). Therefore, the river is most likely a recharging area for the bedrock aquifer and a discharge area for waterbearing units above and perched in the unconsolidated clay material.

#### 2.7 RECEPTORS

The ATC facility is located at 317 Kendall Avenue in Marysville, St. Clair County, Michigan. The facility occupies about 11.2 acres in the South Marysville Industrial Area industrial park. Marysville has a population of about 9,400 people (Marysville Chamber of Commerce, 1992).

The facility is bordered on the north by Kendall Avenue, a manufacturing facility, and a parking lot; on the west by Wills Street and an open lot; on the south by an open lot and an abandoned building; and on the east by Vicksburgh Street and an open lot. The nearest residential area is located about 0.25 mile north of the facility. The nearest school is located about 1.5 miles north of the facility.

The facility is surrounded by a fence and access is controlled by a gate during business hours. Visitors must sign in and have an escort within the facility.

The nearest surface water body, the St. Clair River, is located about 1,400 feet east of the facility and is used for municipal water supply, industrial, irrigation, and recreational purposes. The city of Marysville obtains its drinking water from the St. Clair River from intakes located about 1.75 miles north and upstream of the facility (Marysville Water Department, 1992). The city of St. Clair obtains its drinking water from the St. Clair River from intakes located about 4 miles south and downstream from the facility; this is the nearest drinking water intake downstream from the facility. The St. Clair River Country Club has an intake for irrigation purposes located almost 2 miles downstream from the facility (St. Clair Water Department, 1992). Other surface water bodies in the area include Cuttle Creek, which is located about 0.5 mile north of the facility and flows into the St. Clair River.

Ground water is used for drinking water purposes within a 3-mile radius of the facility. Households existing outside of the municipal water distribution boundaries and west of the facility use ground water obtained from the bedrock aquifer for drinking water purposes (Marysville Water Department, 1992). The nearest drinking water well is located about 1.5 miles west and upgradient from the facility. No ground water wells are known to exist downgradient

of the facility. No industrial wells are known to exist within a 3-mile radius of the site (Marysville Water Department, 1992).

No sensitive environments exist at the facility. A 20-acre wetland is located 0.25 mile west of the facility and another 20-acre wetland is located 0.5 mile southwest of the facility (USGS, 1991). From observations made during the VSI, these wetlands are poorly drained, low areas most likely situated in the impermeable clay of the region. A proposed threatened or endangered species listed for St. Clair County is the Eastern prairie fringed orchid, whose habitat includes wet grasslands (U.S. Fish and Wildlife Service, 1989).

## 3.0 SOLID WASTE MANAGEMENT UNITS

This section describes the nine SWMUs identified during the PA/VSI. The following information is presented for each SWMU: description of the unit, dates of operation, wastes managed, release controls, history of documented releases, and PRC's observations. Figure 2 shows the SWMU locations.

SWMU 1

Hazardous Waste Storage Area

Unit Description:

This unit is located outdoors at the northwest corner of the facility. The unit measures 30 feet by 15 feet and is constructed of a concrete floor and a roof. To contain spills, the floor slopes up at the entrance and has a 6.5-inch concrete berm at the back and along the sides. The unit is surrounded by a 6-foot high chainlink fence that is padlocked at all times. The fence does not have barbed wire but is posted with danger signs.

Date of Startup:

This unit began operation in June 1990.

Date of Closure:

This unit is active for less than 90-day storage of hazardous waste.

Wastes Managed:

This unit manages paint waste (D001), waste isopropanol (D001), waste adhesive (D001), solvent-contaminated waste oil (D001), contaminated and off-specification solvents (D001), and oven dust in 55-gallon drums on pallets. All wastes are transported off site and incinerated.

Release Controls:

The concrete floor of the unit is sloped at the front and has a 6.5-inch berm to contain spills. The unit has a sump with no outlet in the northeast corner for accumulating precipitation. Any spill of hazardous substances would only enter the sump. Drums are bound together to prevent tipping, covered with plastic, and stored on pallets.

History of Documented Releases:

No releases from this SWMU have been documented.

Observations:

The storage area is new and appeared to be in very good condition. Ten 55-gallon drums were in storage at the time of the inspection. Four contained off-specification solvents, three contained waste adhesive, and three contained solvent-contaminated oil. PRC noted no evidence of release (see Photograph No 1).

SWMU 2

Solvents Satellite Accumulation Area

Unit Description:

This unit consists of 55-gallon steel drums equipped with funnels and located indoors in the adhesive mixing and coating areas. The drums are stored on the floor indoors. No floor drains were present near the area of the unit observed.

Date of Startup:

This unit began operation in 1983.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages contaminated solvents (D001) generated during the production of adhesives and application of release coatings. When full, the drums are moved for less than 90-day storage at the Hazardous Waste Storage Area (SWMU 1). The drums are ultimately transported off site and the wastes are incinerated.

Release Controls:

The unit is located indoors, on a concrete floor with no floor drains in the area.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

The drum observed during the inspection appeared to be in good condition. The funnel in one of the drums was open (see Photograph No. 2).

SWMU 3

Gaylord Boxes

Unit Description:

This unit consists of boxes located indoors at two locations in the adhesive manufacturing area of the facility. Each is a 4-foot by 4-foot by 4-foot cardboard box lined with plastic and equipped with

a removable cardboard lid. Each box is stored on a pallet on a concrete floor. At the time of the inspection, the boxes were not located near any floor drains.

Date of Startup:

The facility began using these boxes in mid 1991.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages solvent-contaminated cleaning rags (D001 and F005), dirty adhesive filter socks (D001 and F005), and occasional refuse such as resin bags. The boxes are manifested as contaminated debris transported off site, and incinerated along with their wastes.

Release Controls:

The boxes are lined with plastic, covered with a lid, and stored indoors. The boxes are not stored near floor drains.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

Fire extinguishers were located near the boxes. The floor did not appear to have substantial cracks and no floor drains were observed. PRC was told that the boxes contained filter socks at the time of the inspection. PRC did not look into the boxes to observe the amount of waste accumulated in them. PRC noted no evidence of release (see Photograph No. 3).

SWMU 4

Nonhazardous Liquid Wastes Storage Area

Unit Description:

These units are located inside Building No. 48 and Building No. 7. The unit in Building No. 48 contains 275-gallon plastic bulk tanks enclosed in 4-foot by 4-foot by 4-foot cardboard boxes and used to store waste silicone. The boxes are stored two-high, on pallets, and in several rows. This unit also contains 55-gallon drums to store waste water-soluble oil. The drums are stored two-high, on pallets, and in several rows. The unit in Building No. 7 contains 55-gallon drums containing resin oven drippings and waste oils.

Date of Startup:

These units began operation in 1986.

Date of Closure:

These units are active.

Wastes Managed:

These units manage nonhazardous waste silicone, nonhazardous waste water-soluble oil, nonhazardous resin oven drippings, and nonhazardous waste oil. All of theses liquid wastes are transported off site and incinerated, except for waste oil, which is transported

off site for fuel blending.

Release Controls:

This unit is located indoors on a concrete floor.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

At the time of the inspection 19 boxes and 65 drums were in this unit in Building 48 (see Photograph Nos. 4 and 5). About half of the boxes appeared to be full, only 3 of the drums were empty, and one drum contained silicone. PRC did not observe the unit in Building No. 7.

SWMU 5

Oil/Water Satellite Accumulation Area

Unit Description:

This unit is a 55-gallon drum stored on its side on a stand indoors in the adhesive mixing room. A funnel is inserted into a hole to pour an oil/water mixture into the drum. The stand is about 1.5 feet high which enables a 5-gallon bucket to be placed under a spigot located in the drum's bung. The drum is on its side in order to separate oil and water placed in the drum. The water is poured out of the drum through the spigot into the bucket, moved to the Hazardous Waste Storage Area (SWMU 1), and disposed of off site. The oil is removed from the drum and reused in the mixing equipment.

Date of Startup:

This unit began operation in 1983.

Date of Closure:

This unit is active.

Wastes Managed:

This unit manages an oil and water mixture generated from mixing equipment. The unit is used to separate the oil and water in order to reuse the oil and dispose of the water. The oil is reused in the mixing equipment. The water is placed in 55-gallon drums stored at the Hazardous Waste Storage Area (SWMU 1). The facility refers to this waste as solvent-contaminated oil (D001). The drums are transported off site and incinerated.

Release Controls:

The unit is located indoors on a concrete floor with no drains in the area.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

At the time of the inspection, some oil/water mixture was being poured into the unit. The unit was about half full, probably mostly oil. The unit appeared to be in good condition. No cracks in the floor were visible. PRC observed no evidence of release (see Photograph No. 2).

SWMU 6

Waste Adhesive Satellite Accumulation Area

Unit Description:

This unit is a 55-gallon drum with a plastic liner placed on a rolling base to move it to wherever it is needed. The unit is maintained in the adhesive mixing area of the facility to manage waste adhesive.

Date of Startup:

This unit began operation in 1983.

Date of Closure:

The unit is currently active.

Wastes Managed:

This unit manages waste adhesives (D001). The adhesives are placed in the unit directly, or come from filter socks which are allowed to drip adhesive into the unit prior to disposing of the socks in a Gaylord Box (SWMU 3). When full, the unit is closed and moved to the Hazardous Waste Storage Area (SWMU 1). The wastes are stored at SWMU 1 for less than 90 days and transported off site for incineration.

Release Controls:

The unit is lined with plastic and maintained indoors on concrete

floors.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

At the time of the inspection, one drum was about one-tenth full. It had a filter sock dripping into it (see Photograph No. 6). Another drum was full and awaiting transfer to the Hazardous Waste Storage Area (SWMU 1). Although the floor in the adhesive mixing room had numerous pock marks, it had been painted, which appeared to be acting as a sealant. No release from this unit was

observed.

SWMU 7

Paint Waste Satellite Accumulation Areas

Unit Description:

This unit consists of 55-gallon drums located in the adhesive mixing room and near the coating lines. These drums are used to accumulate residues from 55-gailon drums used for mixing resins and solvents to produce release coating. The facility refers to this

waste as paint waste (D001).

Date of Startup:

This unit began operation in 1990.

Date of Closure:

The unit is active.

Wastes Managed:

This unit manages paint wastes (D001) which are generated from a release coating produced by mixing resins and solvents. The wastes are accumulated in the adhesive mixing room and by the coating lines. The drums of paint waste are then transferred to the Hazardous Waste Storage Area (SWMU 1) and stored for less than 90 days. The wastes are ultimately transported off site and

incinerated.

Release Controls:

The drums are stored indoors and on concrete floors. No cracks in the floors or floor drains were observed in the area of the drums.

History of Documented Releases:

No releases from this SWMU have been documented.

Observations:

At the time of the inspection, one 55-gallon drum of waste in the adhesive mixing room was full, closed, and ready to be transferred to the Hazardous Waste Storage Area (SWMU 1). The facility representative requested that PRC not take a photograph of the drums in the adhesive mixing room because of flammability of the area. PRC did not observe the drums in use near the coating lines. Although the floor in the adhesive mixing room had numerous pock marks, it had been painted, which appeared to be acting as a sealant. No release from this unit was observed.

SWMU 8

Former Hazardous Waste Storage Area

Unit Description:

This former unit was located outside in a courtyard. The unit measured approximately 21 feet by 37 feet and was enclosed by a fence. This unit was used to store hazardous wastes generated at the facility in 55-gallon drums. The drums were stored in secondary containment pans placed on a concrete pad. The unit was located above USTs No. 1 through 3 (AOC 2).

Date of Startup:

This unit began operation in April 1983.

Date of Closure:

The unit became inactive in June 1990, and RCRA closure activities began in November 1990 and are currently ongoing.

Wastes Managed:

Prior to June 1990, solvent-contaminated waste oil (D001), waste adhesive (D001), paint waste (D001), waste isopropanol (D001), and contaminated or off-specification solvents (D001) were stored at this unit. The wastes were transported off site and incinerated.

Release Controls:

The drums were stored in secondary containment pans placed on a concrete pad.

History of Documented Releases:

The releases in the area of this unit are apparently attributable to USTs No. 1 through 3 (AOC 2).

Observations:

At the time of the inspection, the unit no longer existed. The courtyard is composed of gravel. No remedial activities had yet begun. There was no evidence of past releases (see Photograph No. 7).

SWMU 9

Isopropanol Satellite Accumulation Area

Unit Description:

This unit consists of 55-gallon drums located near the coating lines. The unit is used to accumulate waste isopropanol (D001) used to produce a release coating.

Date of Startup:

This unit began operation in 1983.

Date of Closure:

The unit is active.

Wastes Managed:

This unit manages waste isopropanol (D001) used as a release coating. The wastes are accumulated by the coating lines. The drums of waste are then transferred to the Hazardous Waste Storage Area (SWMU 1) and stored for less than 90 days. The wastes are transported off site and incinerated.

Release Controls:

The drums are stored indoors and on concrete floors.

History of

Documented Releases:

No releases from this SWMU have been documented.

Observations:

At the time of the inspection, no drums of waste isopropanol were accumulating. Therefore, no photograph was taken of the unit.

#### 4.0 AREAS OF CONCERN

PRC identified two AOCs during the PA/VSI. These AOCs are discussed below; their locations are shown in Figure 2.

#### AOC 1 USTs No. 202 and 203

USTs No. 202 and 203 are an AOC because they have leaked solvent material. These 20,000-gallon steel tanks were installed in 1982 to store recovered and virgin solvents. ATC notified MDNR of the leaking tanks and excavated the tanks in June 1992. The facility plans to pump and treat the contaminated ground water and remediate the contaminated soil via in situ air stripping pending state approval. New solvent storage tanks have been installed at the location of UST No. 201. At the time of the inspection, the tanks were in the early stages of removal (see Photograph No. 8). ATC retained the services of Techna to manage this project.

## AOC 2 USTs No. 1 through 3

USTs No. 1 through 3 are an AOC because they have leaked solvents and have been involved with numerous spills at the facility. These 12,000-gallon steel tanks were installed in the late 1960s to store toluene and rubber solvent. In 1990, the tanks were emptied, cleaned, and filled with cement. ATC notified MDNR of the leaking tanks and plans to pump and treat the ground water and perform in situ treatment of contaminated soil in conjunction with the RCRA closure of the Former Hazardous Waste Storage Area (SWMU 8). At the time of the inspection, the tanks were buried and no remediation had begun (see Photograph No. 7). The facility is awaiting state approval for the amended closure and remediation plans. ATC has retained the services of Techna to manage this project.

#### 5.0 CONCLUSIONS AND RECOMMENDATIONS

The PA/VSI identified nine SWMUs and two AOCs at the ATC facility. Background information on the facility's location; operations; waste generating processes and waste management practices; history of documented releases; regulatory history; environmental setting; and receptors is presented in Section 2.0. SWMU-specific information, such as the unit's description, dates of operation, wastes managed, release controls, history of documented releases, and observed condition, is presented in Section 3.0. AOCs are discussed in Section 4.0. Following are PRC's conclusions and recommendations for each SWMU and AOC. Table 3, at the end of this section, summarizes the SWMUs and AOCs at the facility and the recommended further actions.

#### SWMU 1

## Hazardous Waste Storage Area

Conclusions:

This unit began operations in June 1990. The unit is well maintained and has an adequate secondary containment structure. The potential for release to environmental media is summarized below.

Ground Water, Surface Water, On-Site Soils: Low. The construction of the unit and the current waste handling practices limit the potential for a release.

Air: Moderate. The unit has no walls and is used to store highly volatile solvents. Any accidental spill occurring at the unit would result in a release to the air.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 2

Solvents Satellite Accumulation Areas

Conclusions:

This unit is maintained indoors near the points of waste generation and has been in use since 1983. The drums are maintained indoors on concrete floors that are in good condition. The drums are ultimately stored in the Hazardous Waste Storage Area (SWMU 1). The potential for release to

environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 3

Gaylord Boxes

Conclusions:

These boxes are maintained indoors near the points of waste generation and have been in use since mid-1991. The boxes are lined with plastic and transported off site immediately from the storage point. Current waste handling practices also limit the potential for release. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 4

Nonhazardous Liquid Wastes Storage Areas

Conclusions:

These units manage nonhazardous wastes, indoors, on concrete floors that are in good condition. Current waste handling practices also limit the potential for release. The containers for the silicone are reused. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 5

Oil/Water Satellite Accumulation Area

Conclusions:

This unit is maintained indoors near the point of waste generation and has been in use since 1983. The oil and water are separated, the oil is reused at the facility and the water is incinerated off site as solventcontaminated waste oil (D001). The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 6

Waste Adhesive Satellite Accumulation Area

Conclusions:

This unit is a plastic-lined 55-gallon drum which manages wastes indoors, on concrete floors that are in good condition near the points of waste generation. This unit has been in use since 1983. Full drums are ultimately stored in the Hazardous Waste Storage Area (SWMU 1). Current waste handling practices also limit the potential for release. The potential

for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 7

Paint Waste Satellite Accumulation Areas

Conclusions:

These units are maintained indoors on concrete floors that are in good condition near the points of waste generation and have been in use since 1990. The wastes are identified as paint because they are composed of resins and solvents. The drums are ultimately stored in the Hazardous Waste Storage Area (SWMU 1). Current waste handling practices also limit the potential for release. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

SWMU 8

Former Hazardous Waste Storage Area

Conclusions:

This former unit was maintained outdoors from 1983 to June 1990. Drums were stored in secondary containment pans. This unit is undergoing closure under RCRA. The current potential for release to environmental media is summarized below.

Ground Water, Surface Water, Air, and On-Site Soils: Low. This unit is no longer active, and no wastes are currently stored at its former location. On-site soil VOC contamination in the area of this unit has been documented, but may be attributable to USTs No. 1 through 3 (AOC 2) located beneath the unit.

Recommendations:

PRC recommends that closure activities for this SWMU continue as scheduled.

SWMU 9

Isopropanol Satellite Accumulation Area

Conclusions:

This unit is maintained indoors on concrete floors that are in good condition near the point of waste generation and has been in use since 1983. The drums are is ultimately stored in the Hazardous Waste Storage Area (SWMU 1). Current waste handling practices also limit the potential for release. The potential for release to environmental media is low.

Recommendations:

PRC recommends no further action for this SWMU at this time.

AOC 1

USTs No. 202 and 203

Conclusions:

A release of solvents from this AOC to ground water and subsurface soils has been documented. The facility is undergoing remediation activities and has replaced the tanks. The potential of a release to surface water is low because of the distance of this AOC to surface water. The potential of a release to air is moderate to high because, at the time of the inspection, the concrete over the tanks was removed and some of the surface soils had been excavated.

Recommendations:

PRC recommends that the extent of ground-water and soil contamination be completely delineated and that the facility proceed with a state-approved remediation plan.

AOC 2

USTs No. 1 through 3

Conclusions:

A release of solvents from this AOC to ground water and on-site subsurface soils has been documented. The facility has closed the tanks in-place, filled them with cement, and will perform remediation activities pending state approval. The potential of a release to air or surface water is low because of the closure of this AOC.

Recommendations:


PRC recommends that the facility proceed with a state-approved remediation plan. The proposed air stripping of the soils should be monitored closely.


RELEASED 6/1/31

PIN #
INITIALS JAV

# TABLE 3 SWMU AND AOC SUMMARY

	SWMU	Dates of Operation	Evidence of Release	Recommended Further Action
1.	Hazardous Waste Storage Area	June 1990 to Present	None	No further action at this time
2.	Solvents Satellite Accumulation Areas	1983 to Present	None	No further action at this time
3.	Gaylord Boxes	Mid 1991 to Present	None	No further action at this time
4.	Nonhazardous Liquid Wastes Storage Areas	1986 to Present	None	No further action at this time
5.	Oil/Water Satellite Accumulation Area	1983 to Present	None	No further action at this time
6.	Waste Adhesive Satellite Accumulation Area	1983 to Present	None	No further action at this time
7.	Paint Waste Satellite Accumulation Areas	1990 to Present	None	No further action at this time
8.	Former Hazardous Waste Storage Area	April 1983 to June 1990	None	Continue scheduled closure activities
9.	Isopropanol Satellite Accumulation Area	1983 to Present	None	No further action at this time





## TABLE 3 (Continued)

## SWMU AND AOC SUMMARY

	AOC	Dates of Operation	Evidence of Release	Recommended Further Action
1.	USTs No. 202 and 203	1982 to June 1992	VOC-contaminated subsurface soils and ground water	Completion of state- approved remedial activities; further ground-water and soil contamination investigation
2.	USTs No. 1 through 3	Late 1960s to 1990	VOC-contaminated soils; history of spills	Completion of state- approved remedial activities

RELEASED (18 0)
RIN #
INITIALS (17)

### REFERENCES

- American Tape Company (ATC), 1983a. RCRA Part A Permit Application, April 29.
- ATC, 1983b. Martin A. Decker, Plant Engineer, Letter to William H. Miner, EPA, May 18.
- ATC, 1983c. Martin A. Decker, Vice President Engineering, Letter to Michigan Department of Natural Resources (MDNR), Surface Water Quality Division, July 8.
- ATC, 1983d. T. Dodd, Interoffice Correspondence to M. Decker, November 18.
- ATC, 1986. Gary W. VanLuven, Production Manager, Letter to Tim Jaski, MDNR, Surface Water Quality Division, April 4.
- ATC, 1988. Martin A. Decker, Vice President Engineering, Letter to Roy Scharmik, MDNR, Water Quality Division, May 4.
- ATC, 1989a. Martin A. Decker, Vice President Engineering, Letter to James Roberts, MDNR, Waste Management Division, March 23.
- ATC, 1989b. Thomas L. Edie, Process Engineering Manager, Letter to Wayne Disposal, Inc., April 26.
- ATC, 1991. Cynthia I. Frantz, Environmental Coordinator, Letter to Tim Jaski, MDNR, Surface Water Quality Division, April 30.
- Armak Company, 1980. Notification of Hazardous Waste Activity Form, August 18.
- Marysville Chamber of Commerce, 1992. Sharon Downs, Telephone Conversation with Jeff Swano, PRC Environmental Management, Inc. (PRC), August 25.
- Marysville Water Department, 1992. Ashley Grant, Assistant Director, Telephone Conversation with Jeff Swano, PRC, August 21.
- MDNR, 1983. R. Dumitru, Interoffice Communication to T. Dodd, December 5.
- MDNR, 1985. Kenneth L. Damrel, Hazardous Waste Division, Letter to Martin Decker, ATC, October 24.
- MDNR, 1988a. Daria W. Devantier, Environmental Quality Analyst, Letter to Martin Decker, ATC, February 29.
- MDNR, 1988b. Report of Oil, Salt or Polluting Material Losses, April 20.
- MDNR, 1988c. Report of Oil, Salt or Polluting Material Losses, September 27.
- MDNR, 1989a. Daria W. Devantier, Environmental Quality Analyst, Letter to Martin Decker, ATC, March 14.
- MDNR, 1989b. Report of Oil, Salt or Polluting Material Losses, April 18.
- MDNR, 1990a. Donald Mbamah, Environmental Quality Analyst, Letter to Martin Decker, ATC, March 29.

- MDNR, 1990b. Alan J. Howard, Chief Waste Management Division, Letter to Martin A. Decker, ATC, June 15.
- MDNR, 1991a. Donald Mbamah, Environmental Quality Analyst, Waste Management Division, Letter to Cynthia I. Franz, ATC, April 5.
- MDNR, 1991b. Donald Mbamah, Environmental Quality Analyst, Waste Management Division, Letter to Cynthia I. Franz, ATC, September 10.
- PRC, 1992. Jeff Swano, Telephone Conversation with Jordan Thompson, Environmental Coordinator, ATC, August 27.
- St. Clair Water Department, 1992. Tom Galvin, Water Plant Operator, Telephone Conversation with Jeff Swano, PRC, August 25.
- Techna Corporation (Techna), 1988. Hazardous Waste Facility Plans and Specifications for Drum Container Storage, Appendix F, June 23.
- Techna, 1991. Sarah Burton, Project Manager, Letter to Alan J. Howard, Chief, Waste Management Division, MDNR, April 29.
- U.S. Coast Guard, 1989. Letter from F. H. Taylor, Hearing Officer, to Martin A. Decker, ATC, March 23.
- U.S. Department of Commerce (USDC), 1968. Climatic Atlas of the United States.
- USDC, 1989. Local Climatological Data, Annual Summary with Comparative Data, Detroit, Michigan.
- U.S. Environmental Protection Agency, 1983. William H. Miner, Chief, Technical, Permits and Compliance Section, Letter to Chris Kurzweil, General Manager, ATC, May 16.
- U.S. Fish and Wildlife Service, 1989. Revised Section 7 Species/County List for Region 3, March 30.
- U.S. Geological Survey, 1991. Port Huron, Michigan-Ontario, 7.5 Minute Series, Topographic Map.
- Warzyn Engineering, Inc., 1990. Phase II Environmental Assessment, ATC, Marysville, Michigan, April.

ATTACHMENT A
VISUAL SITE INSPECTION SUMMARY AND PHOTOGRAPHS

## VISUAL SITE INSPECTION SUMMARY

American Tape Company 317 Kendall Avenue Marysville, Michigan 48040 MID 061 862 926

Date:

March 25, 1992

Primary Facility Representative: Representative Telephone No.:

Mark Fehlmann (313) 364-9000

Additional Facility Representatives:

None

Inspection Team:

Jeff Swano, PRC Environmental Management, Inc. (PRC) Stan Labunski, PRC

Photographer:

Jeff Swano

Weather Conditions:

Clear and warm about 65°F, overcast by noon.

Summary of Activities:

The visual site inspection (VSI) began at 8:00 a.m. with an introductory meeting. The inspection team explained the purpose of the VSI and the agenda for the visit. Facility representatives then discussed the facility's past and current operations, solid wastes generated, and release history. Facility representatives provided the inspection team with copies of requested documents.

The VSI tour began at 11:45 a.m. The tour began outdoors at the Hazardous Waste Storage Area (SWMU 1) and proceeded to the Underground Storage Tanks (UST) No. 202 and 203 (AOC 1) and No. 201. The inspection team went into a warehouse and observed the Nonhazardous Liquid Wastes Storage Area (SWMU 4). A tour of the production facilities followed this and the team observed the Oil/Water Satellite Accumulation Area (SWMU 5), Solvents Satellite Accumulation Area (SWMU 2), Paint Waste Satellite Accumulation Areas (SWMU 7), Gaylord Boxes (SWMU 3), and Waste Adhesive Satellite Accumulation Area (SWMU 6). The tour went outdoors and the inspection team observed the Former Hazardous Waste Storage Area (SWMU 8), and USTs No. 1 through 3 (AOC 2).

The tour concluded at 1:30 p.m., after which the inspection team held an exit meeting with facility representatives. The VSI was completed and the inspection team left the facility at 1:50 p.m.



Photograph No. 1 Orientation: North

Location: SWMU 1 Date: 03/25/92

Description: Hazardous Waste Storage Area. Floor is raised in the foreground and curbed in

the back. Some drums are being stored and are wrapped in plastic.



Photograph No. 2 Orientation: South Description: Solv

Location: SWMU 2 and 5

Date: 03/25/92

Solvents Satellite Accumulation Area (SWMU 2) is on the left. The Oil/Water Satellite Accumulation Area (SWMU 5) is on the right. Drums to the far left contain product. Water is drained out the bottom spigot of oil/water drum.



Photograph No. 3 Orientation: West

Location: SWMU 3

Date: 03/25/92

Description: A typical Gaylord Box. The container is lined with plastic. Fire extinguishers are located nearby.



Photograph No. 4 Orientation: East

Location: SWMU 4 Date: 03/25/92


Description: Silicone is stored in these boxed bulk tanks. These containers are emptied through spigots located at their bottoms. Box at top right is almost full. All containers are marked "Nonhazardous Waste."



Photograph No. 5 Orientation: East Location: SWMU 4 Date: 03/25/92


Description: Waste water-soluble oil is stored in the drums. These drums are located next to

boxes in photograph number 4.



Description: Waste Adhesive Satellite Accumulation Area. The drum is lined with plastic. The filter sock hangs in the drum while the adhesive drains out of it.





Photograph No. 7 Orientation: North Description:

Location: SWMU 8 and AOC 2

Date: 03/25/92

The Former Hazardous Waste Storage Area (SWMU 8) used to be located here. The leaking USTs No. 1 through 3 (AOC 2) are located under the foreground.



Photograph No. 8 Location: AOC 1 Orientation: North Date: 03/25/92

Description: Leaking USTs No. 202 and


203 (AOC 1). Remediation is

currently going on.

Photograph No. 9 Location: New USTs location Orientation: North Date: 03/25/92 Description: Fuel Oil UST N

Fuel Oil UST No. 201. This tank is no longer at the facility and new USTs for solvents have been installed

here.



ATTACHMENT B
VISUAL SITE INSPECTION FIELD NOTES

Interview discussion:	Environmental coordinator pusition	Stan introduces The PA/USI	the inspection.  Cindy Frantz was the	insperational (982-7271 sher	They have another site in	When Jersey that uses all worth-bused processes. Here it is a solveno-base	(Jastun 3/25/92
48 Wednesday Mouth 28 1992 American Tape G. PA/USI 3115/11	Time Arrive: 0150	Weasher Conditions: Clear + warm. Duprast	Freezicu Starr Time: 0800 Inversicu Erd Time: 1115. Pesons Proson Affilation		The same same same same same same same sam	Julius 3/25/92	

The second

lines, line #3 is reinthread tapes; #1+4 are masking After whipping of Goes to continu anuch time goes by (>6 krs) Ir is lained because 100 haz waste + is alumned. Dried in outus, rg overs with NPDES permits. Dus stasfaz (They are competing uf 3M; tape matter is \$3 6:11:21 annual. m) Roll it up and either sell to T. It the barch is rubber in rate, mixes Someone or go to slitting rumed ir beames a 1 1 8 (difes Gwans 3/25/92 sobert; it has been a set since Dow built the fad, ing in the 1940s 1949: The property was divided up as a defenge industry munitions. catalyst to resonature Next, goes to a vitrage mixer, then then it, 550 gallon Whip room, when ready, add totes are Filly + somed. Operation. Taluene is the 1762 would to this beaution major miners, hot + break Processes => Bandunys are down the subbur ma From Port Haran. Javans 3/25/42 batch mixer. and sold.

Environmental in Salvia, durano, Trenches do exist around equipment in Grat ton, Ohio receives because of alleged midnight Incinerators > Ross End. Services Canada. L.m. 8 is gas. Hered; the others see hard our) + laidlaw but they have been had their Some trues they have residuals. Paints come in 53 gallon chains a perturned Sape how six Swal wasre Streams dolains plugged. Jeve 3/25/92 duaping. are electric. width. Then wrap + box; Storage. House, ir is solid waste + drumed+ land Killed. St. Clair County Land Gill (AKA Smith Grek) The dust is respected unil Process. A polyertyless it can't be reused then Electrostaticly applied. For Gration land Gill is Sides of the sape 1811s. Slitting & cart length + dust is applied to the RDS hauls the wastes. Jan 8/25/92 in the future

I barak Rill in your County. contained rubber solvent, tolueur, 101-Rubber blind, Mineral O.l, hisrory of spills + contain. Soils. All tanks edged in place 1990, + 3 in July 1991. Pechna Corp is manaying The LUSTS 36 tanks, 5 /eching. to Wayne Disposal a Class Con taminetal soil want Chain process + Clean up. Comparator, collected by RDS. 20,000 gallons leach. Some In sith air stropping, Leach Compressor, 24-yard Paper, polyothyllae Klm. Hawled I per WK. 2,000 yallons each , Birano 3/25/97 In smiled 196f & 1969. Drum Stordye Mew avea Gooth 35 3/15/42 Water soluble oil & gaes to laidlaw 40 yard you rop compried 2 hours Waste Oils equipment generates. end of April, AToluene tanks. liburates oils a resims which Techna Gorp is managing the Cleanup Put in 1982 (fura 13/25/1/2 LUSTS & Will be replaced by are collected + dummed. Ovender poly 3 Extreme hear Gay lord boxes 3 2 SAAS Goes ro Suffry KHan June, 1991.

Photo Cey: West Gamere J. Sucho Time Dir. Sybject	Case Lease HWSmy WSTS-FT	* # # E = E = E = E = E = E = E = E = E =	1275 N Compactors 1276 Sheycle and 1228 NE downposites 1235 S SAA 1245 L) (Saybork to A	1,205
pump of Treat.	3 tanks clean-closed, in dec 1 1989 ar the east side of 2 The Whip room Convenier 2 Methods (2) 4	2,000 10,000 gallons, 8,000 gul, 2,000 gallons 3 Insalled 1964.	ceased in 1980, 1982, 1990 19 19 1990 10 1990	be replaced by games placed in this area. Never leak- tested but will be closed.  Was filled but never used  (6)

1991 soupling white toluce Oursible of wermix area a condensar (F) vent drips warter outside. Dec. # 13 Placed in cardboard downs, area outside is asphalted 11.2 acres; lasting to acquire sealed + placed in #700 in The wart. Will soon add H & , Gods to RDS hauls. a filter process; well, this additional 1.7 actes at the but they will 48+ 50,16. Drums in Soorage area and checked doily South end of facility. Ewan 3/28/92 Start-up" tape Wouned up Housed by RDS 1 or 2 times associated with cooking waste, 20-yard open rop. 3 times in yr RDS hauls away. In the best all other waste not 40-40 gm typ. =) If one The computer paper & white paper. can't go m'to comporetors. 1 per 2 months. Cardboard ore cousts speel drums. A. Howard han's for free, Reyched must 3 card board, #7 Springhay compactor >> bailed at #11, Evan 3/25/92 9 week. 0) #8 ⊗ #

Their spills are handled in a particular Located in an industrial park. taken way hat NOT regenerared, but instead Am Tape bought 340 puployers, 7 days (wk, appropriate authorities. One spill City, city uses Sr. Clair Filters Environmel, The of ing in material replaced in 1984 Insoulled in 1982 these Godulation Wester Comes Fram Roughly 45,000 165 per way of initality a born of cull Mouns 3/25/92 Sewickley, M. 3 shifts / day. River waren 484,000 gallons purchased last FY, v F,000 gals/wh. Mostly all raw materials are Recorded 2 million yallons Raw materials are brought in by Tanker Mucks once a week, totalling 35,000 Filers. Went to a Pensy land firm for reactive trun. Installed 4 bods. In 1988 remover Fixed-bod carbon absorption Solvens regovery joes through 17 1989. Then #1 + #3 were definered by truck. gallons per mon th. (Jedany 3/15/11 in last FY

Stored, covered with ped in plastic (surrounded, waysped in plastic), Looks real good good Dains in Wirtheasy come, is Sarraynold by 6' fence is Burked wint 6' 2" bin (concret) at north and Sloping up v 6' 2" ar sowah end: Govered 10 Srums An Eltes have been disposed by HW STWage area > Concrete Dumpstwitts per map full of concrete pallers asserted mash 04.1 toler 145 Grans 3/15/92 Techna Gip is of Plymoth, MI (ertified Ataxement remosed Asbestis from the faciliar. in 1988 managed to reach The fiver via the sporm severe Volume disposal received the Sums Soil. Also Marine Billarion Control of Derroit cleaned Environmental did the cheen 4 Find food. Great Lakes Laidlaw 1 in Coruna, Onvario, Ross is in Graffon, Ohio: Ross up in Warren, MI. up 600 gallons Fram Sw. Incinedation Squiles Juzy 3/25/92

1275 Deepe Ingarea is 30

Lear long by 12 feer clap

Constants baired and board of


Constants baired and board of

Brums Some are cleaved.

65 Jams some are cleaved. 1240 Calling # 16 Hrs Satellise waste ware mixed w/ 0; 12 43 (Saylard book containing Skimmed off the bootton & Walte socks & filter Bons of 1820 and also The orth 3/25/92 wanty is accumulation area for accumulated bere-Juan 3/25/92 4 30 feet sonth of compacted 1991 Silizano, water based sorap. on 5 5:34 of barilding. Outdons non harardens liquid vistes. 30°2 (quid 15) 19 houses 23 drums. All somed on pathers. Durum Zerð dumps sen a 15 feet empty. I contains silicone North of Flotzened speel downs Laidlaw sucks for an from sports to caped a boxton of boxton of boxton. All for (sipedra) hars Cardlaw waspe Stowing Wick solution, 3 are Diams contain haste Frank 3/25/92 150

Conting lines. They will fill out the sticker more when the drum is full.

(Batch is willed XP 516)
This into supplied by John La Croix Supplied by Walk Through cutting a real work biller. Find Sate life dumpster for scrap mayls: 1255 Former has waste 3 torage 1505 Sarellift accumulation areq of Silicone waste closed in place. Devans 3/25/92 ape love Finish up. 1515 1335 1510 (Idoum)
1255 Find a drum w/ ( haz was re sticker on it. Mark ranks closed in place particulates out of the product. The washe one is a satellite drum for the 1246 SAA of Spent adhesive (1 down) & waste paint Or the Hour are Squares that redizate dopen's trion why. There are y dryms. I have 26/52/8/ sans 1245 Enget Whip room



STATE OF MICHIGAN

RECEIVED WMD RCRA
RECORD CENTER

NATURAL RESOURCES COMMISSION

> LARRY DEVUYST PAUL EISELE GORDON E. GUYER JAMES P. HILL DAVID HOLLI O. STEWART MYERS JOEY M. SPANO



JOHN ENGLER, Governor

## **DEPARTMENT OF NATURAL RESOURCES**

Stevens T. Mason Building, P.O. Box 30028, Lansing, MI 48909
ROLAND HARMES, Director

October 19, 1992

Ms. Laura Lodisio, HRE-8J U.S. Environmental Protection Agency 77 West Jackson Boulevard Chicago, Illinois 60604-3590

Dear Ms. Lodisio:

SUBJECT: Comments on Draft PA/VSI

American Tape Company Marysville, Michigan MID 061 862 926

Thank you for the opportunity to review the draft PA/VSI for the subject facility. At this time we have no comments. Based on our information, we concur with the recommendations presented in the Executive Summary. In addition, we concur that the facility is an interim status storage facility, and that closure of the container storage unit has not yet been completed.

It should be noted that closure of the former hazardous waste storage area is going to be conducted along with remediation of the leaking underground storage tanks. Representatives of the Waste Management Division and the Environmental Response Division have met with the company to discuss the project, because the company was unable to discern whether the contamination detected is from the underground storage tanks or the hazardous waste storage area. The company is expected to submit a workplan to both divisions that will identify which activities will address appropriate closure requirements. Since proposed remediation is expected to include in-situ remediation for the underground storage tanks area, the Environmental Response Division has agreed to take the lead on this project.

This review is intended to identify major deficiencies in the draft PA/VSI. This review does not represent an exhaustive file search or technical analysis, and does not verify the accuracy of information presented in the draft PA/VSI.

Please contact me at Waste Management Division, Michigan Department of Natural Resources, P.O. Box 30241, Lansing, Michigan 48909, or at the telephone number listed below if you have any questions.

Sincerely,

Kenneth J. Burda, Chief

Hazardous Waste Permits Section

Waste Management Division

517-373-0530

cc: Corrective Action File



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

HRE-8J

March 11, 1992

Mr. Mark Fehlmann Environmental Manager American Tape Company 317 Kendall Avenue Marysville, MI 48040

Re:

Visual Site Inspection American Tape Company MID 061 826 926

Dear Mr. Fehlmann:

The United States Environmental Protection Agency (U.S. EPA) Region V will conduct a Preliminary Assessment including a Visual Site Inspection (PA/VSI) at the referenced facility. This inspection is conducted pursuant to the Resource Conservation and Recovery Act, as amended (RCRA) Section 3007 and the Comprehensive Environmental Response, Compensation, and Liability Act, as amended (CERCLA) Section 104(e). The referenced facility has generated, treated, stored, or disposed of hazardous waste subject to RCRA. The PA/VSI requires identification and systematic review of all solid waste streams at the facility. The objective of the PA/VSI is to determine whether or not releases of hazardous wastes or hazardous constituents have occurred or are occurring at the facility which may require further investigation. This analysis will also provide information to establish priorities for addressing any confirmed releases.

The visual site inspection of your facility is to verify the location of all solid waste management units (SWMUs) and areas of concern (AOCs) to make a cursory determination of their condition by visual observation. The definitions of SWMUs and AOCs are included in Attachment I. The VSI supplements and updates data gathered during a preliminary file review. During this site inspection, no samples will be taken. A sampling visit to ascertain if releases of hazardous waste or constituents have occurred may be required at a later date.

Assistance of some of your personnel may be required in reviewing solid waste flow(s) or previous disposal practices. The site inspection is to provide a technical understanding of the present and past waste flows and handling, treatment, storage, and disposal practices. Photographs of the facility are necessary to document the condition of the units at the facility and the waste management practices used.

The VSI has been scheduled through Cam Slicker of your office for March 25, 1992 at 8:00 a.m. The inspection team will consist of Jeff Swano and Stan Labunski of PRC Environmental Management, Inc., a contractor for the U.S. EPA. Representatives of the Michigan Department

of Natural Resources may also be present. Your cooperation in admitting and assisting them while on site is appreciated.

The U.S. EPA recommends that personnel who are familiar with present and past manufacturing and waste management activities be available during the VSI. Access to any relevant maps, diagrams, hydrogeologic reports, environmental assessment reports, sampling data sheets, environmental permits (air, NPDES), manifests and/or correspondence is also necessary, as such information is needed to complete the PA/VSI.

If you have any questions, please contact me at (312) 886-4448 or Francene Harris at (312) 886-2884. A copy of the Preliminary Assessment/Visual Site Inspection Report, excluding the conclusions and Executive Summary portion will be sent when the report is available.

Sincerely yours,

Kevin M. Pierard, Chief

OH/MN Technical Enforcement Section

Enclosure

cc:

Ken Burda, MDNR - Lansing Dennis Drake, MDNR - Lansing Ben Okwumabua, MDNR

### ATTACHMENT I

The definitions of solid waste management unit (SWMU) and area of concern (AOC) are as follows.

A SWMU is defined as any discernable unit where solid wastes have been placed at any time from which hazardous constituents might migrate, regardless of whether the unit was intended for the management of a solid or hazardous waste.

The SWMU definition includes the following:

- RCRA regulated units, such as container storage areas, tanks, surface impoundments, waste piles, land treatment units, landfills, incinerators, and underground injection wells
- Closed and abandoned units
- Recycling units, wastewater treatment units, and other units that U.S. Environmental Protection Agency has generally exempted from standards applicable to hazardous waste management units
- Areas contaminated by routine and systematic releases of wastes or hazardous constituents, such as wood preservative treatment dripping areas, loading or unloading areas, or solvent washing areas

An AOC is defined as any area where a release to the environment of hazardous wastes or constituents has occurred or is suspected to have occurred on a nonroutine or nonsystematic basis. This includes any area where such a release in the future is judged to be a strong possibility.

PRC requests that, if available, the following facility information be provided during the VSI:

- 1. Two copies of a detailed map of the facility
- 2. Facility history, including dates of operation, ownership changes, and production processes
- 3. Current facility operations
- 4. Processes that generate waste that is treated, stored, or disposed of at the facility
- 5. Records of disposal of wastes generated at the facility (manifests, annual reports, etc...)
- 6. Security at the facility
- 7. Information regarding geology and the uses of ground water and surface water in the area
- 8. Permits (air, NPDES, etc...) the facility currently holds or has held in the past and documentation of any permit violations that may have occurred
- 9. Records of any spills that may have occurred at the facility
- 10. Descriptive operational information (location, dimensions, capacity, materials of construction, etc...), dates of start-up and closure, wastes managed, release controls, and release history for each SWMU

## PRELIMINARY REVIEW

## PREPARED BY

STEVE TUMBARELLO
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION V
230 SOUTH DEARBORN STREET
CHICAGO, ILLINOIS 60604

FACILITY PREPARED FOR

AMERICAN TAPE COMPANY 317 KENDALL AVENUE MARYSVILLE, MICHIGAN 48040 MID 061 862 926

#### Α. **PURPOSE**

The purpose of the Preliminary Review (PR) is twofold: to gather and evaluate existing information on facilities, in order to identify and characterize potential releases, and; to focus the activities to be conducted in the second and third steps of the RFA, the visual site inspection (VSI), and the sampling visit (SV).

#### В. SCOPE

The scope, or area covered by a PR, is to identify areas at a facility which may be releasing hazardous wastes or hazardous constituents that may be harmful to human health and the environment. This involves investigating release potential to all environmental media at the facility (with the exception of ground-water releases from regulated units which is addressed by RCRA and regulated by MDNR), including: ground-water, surface water, air, soils, and subsurface gas.

#### С. FACILITY DESCRIPTION

American Tape, formerly both Armak Co., and then Akzo Manufacturing Co., is located in Marysville, MI, and manufactures pressure sensitive adhesive tapes. The facility is located only about one mile from the St. Clair River, which flows south into Lake St. Clair. The company is filed with the U.S. EPA as both a generator and storer of hazardous waste under facility number MID061862929. The only hazardous waste stored on site is isopropanol alcohol (IPA), a flammable liquid with a UN/NA number of UN-1219. - UW. Colo 6

The hazardous waste storage area is a non-covered rectangle measuring 30

feet long by 25 ft. wide (750 ft<sup>2</sup>). The area is located  $\phi n^2 6 / in$ . concrete pad area. It is secured by an 8 ft. high fence with a locked gate located in the northwest corner of an enclosed courtyard. The courtyard is completely enclosed by buildings with brick walls, on the north and south, and by buildings with concrete walls, on the east and

west.

The waste itself is stored in polyethylene lined 55 gallon drums. Approximately every 6 months a licensed transporter, Tricil Limited MIT270019904, hauls the waste to an incinerator to be burned.

#### FACILITY MANUFACTURING PROCESSES AND DESCRIPTIONS D.

American Tape's manufacturing process for pressure sensitive tapes involves the following steps: adhesive dry mixing, adhesive wet mixing, coating, and slitting. In the dry mix area, natural and/or synthetic rubber, zinc oxide, and various conditioners are mixed (with temperature and time controlled) and then dropped to a roll mill for derating and sheeting. The rubber stock then moves to the wet mix area where it is mixed with resins and, finally, dissolved in rubber solvent. Three blade mixers and one 1200-gallon churn are used in the wet mix area. In the coating area, saturated and released coated paper is coated with

adhesive base coat and top coat. After each coat is applied, the solvent is evaporated in either an infrared or conventional oven at a emperature between 170 and 270°F. The solvent laden air is collected and recycled back into the adhesive. After the top coat dries, the adhesive is further cured at 295-305°C in an oven. Finally, the coated rolls are moved to the slitting area for cutting and packaging.

The manufacturing produces a by-product of 99% isopoparol alcohol (IPA), and 1% water and Du Ponts Quilon. The IPA is, of course, a hazardous material and is stored in the manner described in Part C.

The facility is engaged in an extensive recycling program and their objective is to completely omit IPA generation by 1992.

## E. WASTE CHARACTERISTICS

As previously mentioned, the only hazardous waste generated at American Tape is isopropanol alcohol. The actual concentrations of solvents are 99% IPA and 1% water and Quilin, neither of which are listed EPA hazardous wastes.

The waste is collected in 55 gallon drums and stored in the designated area, after being properly covered, labeled and numbered. After about 1000 gallons of waste is accumulated the waste is shipped to Tricil, LTD., where it is incinerated as a quasi-fuel.

Under RCRA and Act 64 IPA waste is characterized as hazardous because it is ignitable (flash pt. below 140°F).

## F. GEOLOGICAL CONDITIONS/HYDROGEOLOGICAL

The regional geology of Eastern Michigan is summarized in a stratigraphic collumn (Figure 2)

In addition, see Figure 1 for a detailed topographical map of the area surrounding American Tape.

According to Jim Roberts of MDNR, American Tape has not submitted any geological/hydrogeological reports as of January 1, 1989, even though they are required.

## G. RECEPTOR INFORMATION

American Tape is located in Marysville, Michigan. The facility can be found on the Port Huron Quadruple topographical map. It is located 42° 52'410" N latitude and 82°28'570" W longitude. The site is located about 1200 feet west of the St. Clair River. American is located on Township 5NR 17E Section 7 1/4.

The facility is located only about one mile west of Canada, which is on the east bank of the St. Clare River. Immediately north of the facility are sand dunes, and then a golf couse; west of the facility runs the

Port Huron and Detroit Railroad line and further to the west is a marsh. South of the site is largely undeveloped as is the property east of the facility until, of course, one runs into the facility. Only about 1000 \_ft\_north-by-northeast of the facility is a trailer park.

Η.

FILE REVIEW

American Tape, under its former name of Armak (Akzo Chemie American)
filed a Part A application on May 5 1983 On this application in filed a Part A application on May 5, 1983. On this application they claim to only have a container storage area, capable of storing, at most, 12,000 gallons of hazardous wastes. where as 1

#### COMPLIANCE HISTORY Ι.

March 6, 1981; Inspection by MDNR. Major finding of the inspection were: the facility had not analyzed waste, their personnel training records were incomplete, and their contingency plan did not mention any arrangements with local authorities.

September 7, 1982; Inspection by MDNR with the major finding being that no operating record was available as required, per 40 CFR 265.73.

September 4, 1984; Inspection by Larry AuBuchon of the MDNR (Hazardous Waste Division). The major findings were: the annual training was not preformed as required in 40 CFR 265.16, no smoking signs should be placed on the storage area fence as required in 40 CFR 265.17, some containers\_were not in good condition as required in 40 CFR 265.171, hazardous was abels should be placed on the waste drums in storage, and it was strongly recommended that a containment area be built around the storage area.

October 22, 1985; Inspection conducted by Mr. Kenneth Damrel, an Environmental Engineer with MDNR; it was determined that the facility has no deficiencies of the requirements of RCRA in the areas reviewed during the inspection.


October 30, 1986; Letter of warning from MDNR to American Tape detailing apparent violations of the Michigan Hazardous Waste Management Act, 1979 PA 64, Part 7 (the MNDR equivalent of 40 CFR Part 265, Subpart H) for the following reasons: failure to provide adequate financial assurance coverage for closure/post-closure costs (i.e., trust agreement, security bond, letter of credit, certificate of insurance, financial test, etc., and, failure to provide adequate coverage for sudden accidental occurrences (i.e., liability insurance and/or financial test). - - 1 34 6

April 22, 1987; American Tape included a copy of performance bond assuring coverage for closure and post-closure cost for the files. Also, American mailed a copy of invoice, which has been paid for present period.

## J. <u>SOLID WASTE MANAGEMENT UNITS</u>

On their certification regarding potential releases from solid waste management units the facility indicated that it had no SWMUs. No contradictory evidence was found to dispute this, and this will be verified during the VSI.

- Delamore 187



		-10-		SUBSURFAC FEET	•
				BSUI ET	
COLUMN C - ROC		1		SG E	
LOWER PENINSULA	., <u>OR</u> FOUND I	N THE SUBSURFACE \		. !	
BY DRILLING		**************************************	COUE AVECTOR	Z S	
BOCK GROUPS	ROCK FORMATIONS	FORMATION MEMBERS	SOME INFORMAL TERMS USED IN SUBSURFACE	76	
			PETROLEUM WORK	APPROX. THICKNES	
GLACIAL DE	HFT, LATE PLEIS	TOCENE DE COMO	á	포	
	f		1	1	
	RED BEDS , UNA	NAMED, ?LATE JURASSIC?	ïl	220	
Control of the Contro	GRAND RIVER	IONIA EATON AND			
	SAGINAW	WOODVILLE SANDSTONES		750	<del>t</del>
	FORMATION	VERNE LIMESTONE	PARMA SANDSTONE	ł	
	BAYPORT LIMESTO	NE ·· -		160	
	• .	. /	"TRIPLE GYP" BROWN LIME	1	
GRAND RAPIDS	MICHIGAN	/	STRAY-STRAY SANDSTONE-GAS STRAY DOLOMITE	600	
	R(C1110 A)	NAPOLEON SANOSTONE	STRAY DOLOMITE STRAY SANDSTONE - GAS, OIL	<del> </del>	-
	MARSHALL	I SEEGH CHARGOTONE	MARSHALL SANDSTONE	330	ļ
		LOWER MARSHALL SS.	GAS, QIL		] .
	COLDWATER	"MARSHALL" SANDSTONE	COLDWATER LIME WEIR SAND - GAS	1300	•
	SHALE (WEST)	(EAST)	WEIR SAND - <u>GAS</u> COLDWATER RED - ROCK "BEREA" (W. MICH.) - <u>OIL</u> , <u>GAS</u>	-	{
	(W. MICH.)	. —	BEREA SAND (E. MICH.) - OIL, GAS	\$ 1320	1
	ANTRIM SHALE	İ			
<u> </u>	E MICH.)	<del></del>	SQUAW BAY - OIL, GAS		1
	LIMESTONE		1		
			TRAVERSE FORMATION TRAVERSE LIME - OIL, GAS STONEY LAKE ZONE - OIL, GA (UPPER TRAVERSE IN W. MICH		
	1		STONEY LAKE ZONE - OK GA	Ś Is	į.
TRAVERSE	]		COFFER TRAVERSE IN W. MICH	830	1
GENERALLY	1				1
UNDIVIDED IN				i	
SUBSURFACE	ALPENA LS.				
=	ŧ				
<b>=</b>					
	BELL BOATS				
	ROGERS CITY LS.		ROGERS CITY LS OIL GAS	<del>                                     </del>	i
	DUNDEELIMESTONE		DUNDEE LIMESTONE - OIL, GAS	475	
	1		REED CITY ZONE - OIL GAS	1	7
DETROIT RIVER	LUCAS FORMATION		REED CITY ZONE - OIL, GAS SOUR ZONE - OIL, GAS RICHFIELD ZONE, OIL, GAS	1450	
	AMHERSTBURG FM.			I	]
	BOIS BLANC FORM		<del> </del>	100	
	ORNOER BEARD	<del></del>	<del></del>		ี่ 1
BASS ISLANDS				700	
	G UNIT			i	Į
	F EVAPORITES E UNIT		E-ZONE (OR KINTIGH \ ZONE) <u>OIL</u>		Ì
SALINA	D EVAPORITE C UNIT				į
	B EVAPORITE A-2 CARBONATE		A-2 DOLOMITE - GAS	3150	1
■.	A-2 EVAPORITE A-1 CARBONATE		A-2 LIME - GAS		
<b>=</b> ,`	A-I EVAPORITE		A-! DOLOMITE - OIL,GAS	<u> </u>	<u>i</u>
			GRAY NIAGARAN - OIL GAS	4.22	
NIAGARA		,	WHILE MINGAKAN	980	i
			HULLITON WHALE (E. MICH.)	<u> </u>	4
CATARACT	MANITOULIN DOL.	<u>:                                      </u>	1	2003	
	QUEENSTON SHALE		+	1	†
RICHMOND					
				950	i
EDEN	UTICA SHALE	COLL MCWOOD SHALE	TOSHTON COCKE OF	1	1
TRENTON -	-	COLLINGWOOD SHALE	TRENTON GROUP - OIL, GAS BLACK RIVER FM OIL, GAS	1100	1
BLACK RIVER			BLACK RIVER SHOIL, GAS	1100	ì
(UNDIVIDED)		GLENWOOD	VAN WERT ZONE - OLL, GAS	260	<u>.</u>
<u></u>	ST. PETER SS.		<del></del>	260	7
PRARIE DU CHIEN	NEW RICHMOND SS.		1	425	İ
	ONEOTA DOLOMITE	JORDAN SANDSTONE	ONEOTA DOLOMITE - DIL	<u> </u>	4
	TREMPEALEAU	LODI DOLOMITE	<u> </u>	750	1
LAKE SUPERIOR	FORMATION SE	ST. LAWRENCE DOLOMITE	<del></del>	<del> </del>	7
THE SUPERIOR	DRESBACH SS.	1		(175?	
	EAU CLAIRE FM.	]	1	"""	
www.	MOUNT SIMON SS		<del> </del>	1100	<del>.</del> -
	JACOBSVILLE SS.	The state of the s	PARTY TOTAL	19 125	_
PRE-CAMBRIAN -	GNEOUS, METAMO	RPHIC SEDIMENTARY RO	DCKS BENEA	13,125 TH AN	(NOT ALL IY ONE
			POINT)		
EVAPORITE (HALI COAL CARBONATE REI ORIGIN	TE, GYPSUM, OR EFS OR BIOHERM	S OF ORGANIC	MAJOR EROSIONAL GAP THESE AGES MISSING ELSEWHERE. UNCONFOR	RERE; RMITY.	MAI DE FRES

week of Area Chame



January 22, 1986

RCRA Activities Region V P.O. Box A3587 Attention: ATKJG Chicago, Illinois 60690

Attn: Mr. David A. Stringham

Chief, Solid Waste Branch

RE: American Tape Co.

MID 061862926

Hazardous Waste Permit Application

Dear Mr. Stringham:

Please find enclosed certification regarding potential releases from solid waste management units. A name change from Armak (Akzo Chemie American) to American Tape Co. was requested and granted after tape division was sold April 1983.

I have also enclosed a copy of Site Inspection Report dated October 24, 1985. If you have any additional questions, please contact me at 313-364-9000.

Sincerely,

Martin Decker
Martin Decker
Vice President
Engineering

MAD/dja

Enclosed:
Certification
1985 Inspection Report

Sent as registered mail.

## CERTIFICATION REGARDING POTENTIAL RELEASES FROM SOLID WASTE MANAGEMENT UNITS

FACILITY NAME:	American Tape Co.
EPA I.D. NUMBER:	MID 061862926
LOCATION CITY:	317 Kendall Ave., Marysville
STATE:	Michigan 48040
closed) at your	of the following solid waste management units (existing or facility? NOTE - DO NOT INCLUDE HAZARDOUS WASTE UNITS NOTE OF THE N
Storage Tand Container Some Injection Wastewater Transfer St Waste Recycowaste Treat Other	k (Above Ground)  k (Underground)  torage Area  ells  Treatment Units   X  X  X  X  Currently shown in our X  part A application.
of in each uni would be consi RCRA. Also in disposed of an of each unit a	t. In particular, please focus on whether or not the wastes dered as hazardous wastes or hazardous constituents under aclude any available data on quantities or volume of wastes at the dates of disposal. Please also provide a description and include capacity, dimensions and location at facility.
UN-1219 Was	te Isopropyl Alcohol is stored in 55 gallon drums in our
hazardous w	aste storage area 25 feet x 30 feet. During 1985 1,000
gallons was	removed and incinerated by Tricil Limited. Ontario. Canada
MIT 2700199	004.

NOTE: Hazardous wastes are those identified in 40 CFR 261. Hazardous constituents are those listed in Appendix VIII of 40 CFR Part 261.

រាក	the units noted in Number 1 above and also those hazardous waste units our Part A application, please describe for each unit any data avail- on any prior or current releases of hazardous wastes or constituents
to	he environment that may have occurred in the past or may still be rring.
Ple	se provide the following information
С.	Date of release Type of waste released Quantity or volume of waste released Describe nature of release (i.e., spill, overflow, ruptured pipe or tank, etc.)
N	ne
А	erican Tape Co. started April 30, 1983.
In ple whi tha haz	egard to the prior or continuing releases described in Number 3 above, se provide (for each unit) any analytical data that may be available h would describe the nature and extent of environmental contamination exists as a result of such releases. Please focus on concentrations rdous wastes or constituents present in contaminated soil or groundwatene
In ple whi tha haz	egard to the prior or continuing releases described in Number 3 above, se provide (for each unit) any analytical data that may be available h would describe the nature and extent of environmental contamination exists as a result of such releases. Please focus on concentrations rdous wastes or constituents present in contaminated soil or groundwater
In ple whi tha haz	egard to the prior or continuing releases described in Number 3 above, se provide (for each unit) any analytical data that may be available h would describe the nature and extent of environmental contamination exists as a result of such releases. Please focus on concentrations rdous wastes or constituents present in contaminated soil or groundwatene

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the submittal is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. (42 U.S.C. 6902 et seq. and 40 CFR 270.11(d))

Martin Decker Vice President Engineering
Typed Name and Title

Martin Decker Vice President Engineering
Typed Name and Title

Signature

January 21, 1986 Date

## CONTINUING EXLEASES AT PERMITTED PACILITIES

SEC. 206. Section 3004 of the Solid Waste Disposal Act is amended by adding the following new subsection after subsection (t) thereof:

"(u) Continuing Releases at Prescript Facilities.—Standards promulgated under this section shall require, and a permit issued after the date of enactment of the Hazardous and Solid Waste Amendments of 1984 by the Administrator or a State shall require, corrective action for all releases of hazardous waste or constituents from any solid waste management unit at a treatment, storage, or disposal facility seeking a permit under this subtitle, regardless of the time at which waste was placed in such unit. Permits usued under section 3005 shall contain schedules of compliance for such corrective action (where such corrective action cannot be completed prior to issuance of the permit) and assurances of financial responsibility for completing such corrective action."